# Designations in the drawings for the article of P. N. Rybkin.

*A* is the antenna.
*P* is the coherer or radio conductor.
*c* is the shock or shock.
*D* - extension coil.
*U* - autotransformer (transform. Uden).
*Kl* is the transmitting key.
*K* is the capacitor.
*L* - Leiden bank.
*h* - grounding.
*And* - induction apparatus (when it indicates the maximum length of its spark).
*and* - the spark gap (when it indicates its length).
*n* - breaker.
*k* is the capacitor to the breaker.
*B* - battery of elements.
*Sat* - without induction resistance.
*P* - relay.
*T* is the telephone.
*M* is the Morse apparatus.